

Computer	Slot	Result	Notes
Dell9100	1	Pass	
Dell9100	4	Pass	
HPXw4200	1	Pass	
HPXw4200	7	Pass	
T5500	1	Fail	(1) no hot plug
T5500	3	Fail	(1) no hot plug
T5500	4	Pass	
Z800	1	Pass	
Z800	3	Pass	
Z800	4	Pass	
Z800	5	Fail	(1) no hot plug
Z800	7	Fail	(1) no hot plug
Z820	1	Pass	
Z820	3	Fail	(1) no hot plug
Z820	4	Fail	(1) no hot plug
Z820	5	Fail	
Z820	6	Pass	
Z210	1	Pass	
Z210	2	Pass	
Z210	3	Pass	
EVGA-SRX	1	Fail	
EVGA-SRX	2	No Test	Video card in slot 2
EVGA-SRX	3	No Test	Video card in slot 2
EVGA-SRX	4	Pass	
EVGA-SRX	5	Pass	
EVGA-SRX	6	Pass	
EVGA-SRX	7	Pass	
ASUS-Z9PE	1	Pass	
ASUS-Z9PE	2	Pass	
ASUS-Z9PE	3	Fail	(2)Link doesn't start
ASUS-Z9PE	4	Fail	(2)Link doesn't start
ASUS-Z9PE	5	Fail	(2)Link doesn't start
ASUS-Z9PE	6	Fail	(2)Link doesn't start
ASUS-Z9PE	7	Fail	(2)Link doesn't start
GA-Z77X-UP5TH	1	Fail	
GA-Z77X-UP5TH	2	Fail	
GA-Z77X-UP5TH	3	Pass	
GA-Z77X-UP5TH	4	Pass	
GA-Z77X-UP5TH	5	Fail	(2)Link doesn't start
GA-Z77X-UP5TH	7	Fail	(2)Link doesn't start

(1) – this problem is now understood and will be fixed in a future release

(2) – this is a hardware problem, the PCIe link does not start