



macOS High Sierra Compatibility

12/20/2017

PCIe Cards	PART NUMBER	Compatible with macOS High Sierra
Allegro FireWire 400 PCIe Card (3 ports)	FW400A-E	√
Allegro FireWire 800 PCIe Card (3 ports)	FW800-E	√
Allegro USB 2 [Discontinued]	USB2-E	√
Allegro USB 3 PCIe Card 4-port (Fresco Logic)	USB3-4PM-E	√
Allegro Pro USB 3 PCIe Card 4-port (Fresco Logic)	USB3-PRO-4PM-E	√
Allegro USB 3 PCIe Card 2-port (NEC - Discontinued)	USB3-2PM-E	No
Allegro USB USB-C 10Gb 2-port	USB3C-2PM-E	√
Presto Gigabit Ethernet Pro (Marvell - Discontinued)	GE1000LA-E	√
Presto Gigabit Ethernet Pro (Broadcom)	GE1000LAB-E	Pending ⁽⁵⁾
Presto Gigabit Ethernet Server 2-Port (Intel)	GE1000LA2XA-E	√
Presto 10GBASE-T Ethernet 2-Port (Intel)	G10E-2X-E3	√ ⁽¹⁾
Presto 10GBE SFP+ Ethernet 2-Port (Intel)	G10E-SFP-2XA-E2	√ ⁽¹⁾
Presto SFP+ Ethernet 1-Port (Myricom - Discontinued)	G10E-SFP-E	√ ^(1,2)
Presto SFP+ Ethernet 2-Port (Myricom - Discontinued)	G10E-SFP-2X-E2	√ ^(1,2)
Sonnet/ATTO H680 SAS Controller (8-port)	SAS8-E2	√ ^(1,3)
Sonnet/ATTO R680 DX8/RX16 6Gb SAS RAID Controller	FUS-RC6-E2	√ ^(1,3)
Sonnet/ATTO R380 D8/R8 3Gb RAID Controller (Discontinued)	FUS-RC-E	No
Sonnet/ATTO 8Gb Single Channel Fibre Channel	FIBRE-81-E2	√ ^(1,3)
Sonnet/ATTO 16Gb Single Channel Fibre Channel	FIBRE-161-E3	√ ^(1,3)
Tango FireWire/USB	FWUSB2A-E	√
Tango FireWire 800/USB	FW8USB2A-E	√
Tango 3.0 FireWire 800/USB 3	FW8-USB3A-E	√
Tempo Duo (2 eSATA + 2 USB 3 ports)	TSATA6USB3-E	√
Tempo PCIe SSD	PCIE-SSD1-512-E	√
Tempo PCIe 3.0 SSD	PCIE-SSD-05-E3	√
Tempo SATA E2P PCIe Card (2 ports)	TSATAII-E2P	No
Tempo SATA E4i PCIe Card (4 internal ports)	TSATAII-E4i	√ ⁽¹⁾



macOS High Sierra Compatibility

Tempo SATA E4P PCIe Card (4 external ports)	TSATAII-E4P	√ ⁽¹⁾
Tempo SATA 6Gb (2 ports) (Marvell)	TSATAIII-E2-E2	√
Tempo SATA Pro 6Gb (2 ports) (ASMedia)	TSATA6-PRO-E2	√
Tempo SATA Pro 6Gb (4 ports) (Marvell)	TSATA6-PRO-E4	√
Tempo SSD	TSATA6-SSD-E2	√ ⁽⁴⁾
Tempo SSD Pro (Marvell – Discontinued)	TSATA6-SSDP-E2	√ ⁽⁴⁾
Tempo SSD Pro Plus (ASMedia)	TSATA6-SSDPS-E2	√ ⁽⁴⁾
Thunderbolt 3 Expansion Chassis		
Echo Express SEL	ECHO-EXP-SEL	√
Echo Express SE I	ECHO-EXP-SE1	√
Echo Express SE II	ECHO-EXP-SE2	√
Echo Express III-D	ECHO-EXP3FD	√
Echo Express III-R	ECHO-EXP3FR	√
Thunderbolt 2 Expansion Chassis		
Echo Express SEL	ECHO-EXP-SEL	√
Echo Express SE I	ECHO-EXP-SE1	√
Echo Express SE II	ECHO-EXP-SE2	√
Echo Express III-D	ECHO-EXP3FD	√
Echo Express III-R	ECHO-EXP3FR	√
xMac mini Server	XMAC-MS-A	√
xMac Pro Server	XMAC-PS	√
External Graphics		
Breakaway Box	GPU-350W-TB3Z	√ ⁽⁶⁾
Breakaway Box Developer Edition	GPU-350W-TB3DEK	√ ⁽⁶⁾
Breakaway Box 550	GPU-550W-TB3	√ ⁽⁶⁾
Radeon RX 560 eGFX Breakaway Puck	GPU-RX560-TB3	Pending ⁽⁸⁾
Radeon RX 570 eGFX Breakaway Puck	GPU-RX560-TB3	√ ⁽⁶⁾



macOS High Sierra Compatibility

Thunderbolt Media Readers/Dock/Adapters		
Echo 15+ Dock	ECHO-DK-xxx	√
Echo ExpressCard Reader	ECHO-E34	√ ⁽⁹⁾
Echo ExpressCard Pro Reader	ECHOPRO-E34	√ ⁽⁹⁾
SF3 Series - CFAST 2.0 Pro Card Reader	SF3-2CFST	√
SF3 Series - SxS Pro Card Reader	SF3-2SXS	√
Thunderbolt Pro P2 Card Reader	TB-P2	√
QIO Professional Media Reader (Discontinued)	QIO-xxx	Partial ⁽⁸⁾
USB 3.0 + eSATA Thunderbolt Adapter	TB-USB3SATA	√
USB 3.0 + Gigabit Ethernet Thunderbolt Adapter	TB-USB3GE	√
Thunderbolt Storage		
Fusion Thunderbolt 2 PCIe Flash Drive 256G	FUS-TB2-256GB	√
Fusion Thunderbolt 3 PCIe Flash Drive 1TB	FUS-TB3-1TB	√
Thunderbolt TWIN 10G		
Twin 10G Thunderbolt 2 to Dual Port Copper	TWIN10G-TB2	√
Twin 10G Thunderbolt 2 to Dual Port Copper	TWIN10GC-TB2	√
Twin 10G SFP+ Thunderbolt 2 to Dual Port SFP+	TWIN10G-SFP-TB2	√
Twin 10G Thunderbolt 3 to Dual Port Copper	TWIN10GC-TB3	√
Twin 10G SFP+ Thunderbolt 3 to Dual Port SFP+	TWIN10GC-SFP-T3	√
ExpressCard/34 Cards		
Allegro USB 3 (2 ports) (Fresco Logic)	USB3-2PMA-E34	√
Allegro USB 3 (2 ports) (NEC – Discontinued)	USB3-2PM-E34	No
FireWire USB 2 (2 FireWire + 1 USB ports)	FWUSB2-E34	√
FireWire 800 Pro	FW800-E34	√
Multimedia Memory Card Reader & Writer	MMRW-E34	√
SDHC Adapter	SD-SXS-E34	√
Presto Gigabit Ethernet Pro (Broadcom)	GE1000LAB-E34	Pending ⁽⁵⁾
SDXC UHS-I Reader/Writer (Discontinued)	SDXC-UHSI-E34	No



macOS High Sierra Compatibility

Tempo SATA Pro 6Gb (1 port)	TSATA6-PRO1-E34	√
Tempo SATA Pro 6Gb (2 port)	TSATA6-PRO2-E34	√
Tempo SATA Duo 6Gb & USB 3 (2+2 ports)	TSATA6USB3-E34	√
USB 2.0 Hub (4 ports)	USB2-4P-E34	√

- (1) Must reinstall driver and authorize manufacturer in Security and Privacy System Preferences.
- (2) Myricom NIC cards no longer supported by Sonnet. Contact [CSPi](#) for support. CSPi does not officially support macOS 10.13, but the drivers appear to work.
- (3) Updated drivers available from [ATTO Technologies](#).
- (4) Booting from RAID is not supported in High Sierra.
- (5) The Presto Gigabit Ethernet Pro uses an Apple macOS native driver. Sonnet has filed a bug report with Apple.
- (6) See [support page](#) for more information about Graphics card and Mac compatibility.
- (7) The RX560 is not yet compatible with macOS High Sierra. See [support page](#) for more information.
- (8) P2 functional. SxS cards hot plug only when connected over Thunderbolt. CF cards don't mount.
- (9) To read SxS cards, must reinstall [Sony driver](#) and authorize manufacturer in Security and Privacy System Preferences.